

From: [Miller, Garyg](#)
To: [Foster, Anne](#)
Cc: [Sanchez, Carlos](#)
Subject: FW: Submerged equipment
Date: Monday, March 21, 2016 1:08:30 PM

Anne - FYI

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: Owens, Rock (CAO) [mailto:Rock.Owens@cao.hctx.net]
Sent: Wednesday, March 16, 2016 8:38 AM
To: Miller, Garyg <Miller.Garyg@epa.gov>
Cc: Allen, Bob (PCS) <Bob.Allen@pcs.hctx.net>; O'Rourke, Terence (CAO) <Terence.O'Rourke@cao.hctx.net>; Soard, Robert (CAO) <Robert.Soard@cao.hctx.net>; Utley, Sarah (CAO) <Sarah.Utley@cao.hctx.net>; Earnest Wotring <EWotring@BakerWotring.com>
Subject: Submerged equipment

Gary

Sorry I missed you when I called this morning. I just received the attached photos of the work at the San Jacinto River Waste Pits. I was told they were taken yesterday afternoon and allegedly depict a piece of equipment being used to repair the most recent damage to the CAP discovered back in February. Can you verify this for me?

I'd also like to discuss the implications this and other recent events has on allowing continued work by the PRPs consultant and its contractors at the site. Please give me a call at your earliest opportunity.

Regards

Rock Owens



9761923